

# e-ASK Demonstration Fixture

## Operation Instructions



### Using this Guide

Some Monaco RVs (includes *Monaco, Holiday Rambler, Beaver, and Safari*) with the Doorbell version of the TriMark e-GRAB Handle or the embedded e-PAD have the doorbell button of the keypad directly connected to the doorbell device inside the RV. The type of doorbell being controlled by the keypad requires much more than the 500mA that the keypad is rated for, and will eventually destroy the keypad. To prevent this from happening, or to retrofit a replacement so that it does not happen again, a relay must be installed to electrically isolate the keypad from the doorbell.

### Do you need this guide?

The vehicles that have shown this kind of failure were model years 2007, 2008, and in rare cases 2009. Later models do not need this fix. The way to tell is to find your vehicle's doorbell fixture. If it is a *chime-style doorbell* with chimes in the fixture, then you will need this fix. The *chime-style doorbell* pulls between 2 and 10 Amps through the keypad. If it is a *piezo-electric doorbell* with a speaker instead of chimes, you may still need this fix. The *piezo-electric doorbell* pulls less than 500mA through the keypad during normal operation, but its design makes it susceptible to passing voltage spikes from other devices through the signal wire to the keypad, resulting in similar damage. If your *piezo-electric doorbell* has a large capacitor soldered between the power and ground wires (not the signal wire) near where they enter the doorbell, then your vehicle's doorbell design is safe and this fix is not necessary.

### Finding the Doorbell Wiring

The wire connecting the doorbell to the keypad must be traced to ensure that there is not already a relay in place. If there is already a relay in the doorbell control wire, and the doorbell system has failed, then the relay may be faulty and should be replaced instead of, or in addition to, the keypad.

The best place to start is at the doorbell. If the doorbell cannot be found, contact the manufacturer of the RV to determine where the likely mounting locations are. If the doorbell is still functional, triggering the doorbell can aid in locating it, but each time the doorbell is activated without this problem fixed greatly reduces the life expectancy of the keypad.



# e-ASK Demonstration Fixture Operation Instructions




## Modifying the Doorbell Wiring

1. Cut the wire connecting the keypad to the doorbell near an area that can conveniently mount a relay, such as near a hidden wall or electrical cabinet.
2. Run a +12V and a Ground wire to the location where the relay will be mounted.
3. Wire the relay according to the schematic below.
4. Test the doorbell for proper operation with the keypad.

*NOTE: Colors shown below are based on the colors of the wires coming out of the keypad based on production in 2010. Your colors may vary depending on Monaco's coach harness and some color changes in TriMark production between 2007 and 2010. The doorbell signal wire will be the only wire that is routed from the keypad towards the doorbell.*

## Wiring Diagram - Doorbell Keypad Doorbell Output

Notes: Cut the purple wire from the rest of the harness and route it to Pin 86 on the new relay  
Connect +12V to Pin 85 on the relay  
Connect GROUND to Pin 87 on the relay  
Connect the doorbell to Pin 30 on the relay  
Ignore 87a, it is not used.



# e-ASK Demonstration Fixture Operation Instructions



**TriMark Corporation**  
500 Bailey Avenue  
P.O. Box 350  
New Hampton, IA 50659  
United States  
Tel: +1 641 394 3188  
Fax: +1 641 394 2392  
E-mail: [tips@trimarkcorp.com](mailto:tips@trimarkcorp.com)  
[www.trimarkcorp.com](http://www.trimarkcorp.com)

**TriMark Europe Limited**  
Cedar Court  
Walker Road  
Bardon Hill  
Coalville, LE67 1TU  
United Kingdom  
Tel: +44 (0) 1530 512460  
Fax: +44 (0) 1530 512461  
E-mail: [sales@trimarkeu.com](mailto:sales@trimarkeu.com)  
[www.trimarkeu.com](http://www.trimarkeu.com)

**TriMark (Xuzhou)**  
**Automotive Components Co. Ltd**  
Standard Factory Building A5  
Jingwu Road  
Xuzhou Economic Development Zone  
Xuzhou, Jiangsu, 221004 PR China  
Tel: +86 516 8773 0018  
Fax: +86 516 8773 0058  
E-mail: [sales@trimarkcn.com](mailto:sales@trimarkcn.com)  
[www.trimarkcn.com](http://www.trimarkcn.com)